

September 17, 2012

MEMORANDUM

TO:

District Board of Trustees

FROM:

Jim Murdaugh, President

SUBJECT:

Annual SREF Fire, Sanitation and Casualty Inspection

Item Description

This item provides an update of the annual SREF Fire, Sanitation and Casualty Inspection reports.

Overview and Background

The State Requirements for Educational Facilities (SREF) and Florida Statutes mandate that the College perform an annual safety inspection for all TCC sites and facilities. The College is required to correct the noted deficiencies by June 30 of each year.

At the time of this writing, the remaining items at the Gadsden Center have not been completed. These items have been in progress and are expected to be completed within the next several weeks. Under the terms of our lease with Gadsden County, all maintenance and corrections at this building are the responsibility of the County.

Past Actions by the Board

The District Board of Trustees has approved the submitted reports on an annual basis.

Funding/Financial Implications

All costs to correct deficiencies, with the exception of the Gadsden Center building, are funded from the Physical Plant operating budget and PECO funds in the appropriate categories.

Staff Resource

Teresa Smith

Recommended Action

No additional action is required at this time.

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION

ADMINISTRATIVE RULE - SREF 2008 & F.A.C. 69A-58 FISCAL YEAR 2011-2012						
College Facility: SCHOOL / FACILITY: ADDRESS:	Tallahassee Community College Satellite Facilities and Leased Facilities 444 Appleyard Drive, Tallahassee, FL 32304	FIRE DISTRICT: Various		# OF SERIOUS FIRE SAFETY VIOLATIONS _0		
		Distriction (trans		# OF NON-SERIOUS FIRE SA	October 26, 2011	
FIRE DISTRICT FIRE SAFETY IN	SPECTOR NAME PRINTED (IF JOINT INSPECTION)	SCHOOL BOARD FIRESAFETY			INSPECTION DATE	
FIRE DISTRICT FIRE SAFETY IN	SPECTOR SIGNATURE (IF JOINT INSPECTION)	Fire Prevention Spe	ecialists, Inc., 609 Gina L	ane, Melbourne, FL 32940	321-757-7205 05523	
SIGNATURE DATE	FIRE INSPECTOR CERTIFICATION NUMBER	COMM COLLEGE BOARD FIRE	SAFETY INSPECTOR SIGNATURE /		ICATION NUMBER	
specifically identified. F	eading into that particular room. Or if the de or example: Pressbox, Field House, Pavillic College has met the requirements of F.S.S.	on, etc.				
Approval of Reports by B	loard (including Letter)YESNO					
THE UNDERSIGNED ATT DEFICIENCIES.	ESTS TO THE REVIEW OF THIS REPORT IN	ITS ENTIRETY AND ACKNOWLE	DGES AWARENESS OF TH	E DISCOVERED		
FACILITY ADMINISTRATOR NAME	PRINTED	F	ACILITY ADMINISTRATOR SIGNATUR	RE		
FACILITY ADMINISTRATOR TITLE		3	SIGNATURE DATE	The second secon		

CODE NUMBER	Insp. Initials		Prior Times Ciled	Deficiency Corrected By	Date Deficiency Corrected	Line No.
		Location, Deficiency Description				
	RC	Brogan Museum: No deficiencies noted				1
					4440131	2
FFPC 1, 4.5.8.1	RC	Wakulfa Center: Emergency lights inoperable in office area and east classroom	0	6-30-12	11/12/11	3
					Camplete	4
NFPA 70, Art. 110.26	RC	CCLA North Hall Closet: Electrical panels obstructed	2	6-30-12	Complete	5
NFPA 70, Art. 110.26	RC	CCLA W-14: Many electrical panels obstructed	2	6-30-12	Complete	6
					11/15/11	7
FFPC 1, 4.5.8.1	RC	Quincy House, 1st Floor Hall: Exit light battery dead	11	6-30-12	11/15/11	8
FFPC 1, 4.5.8.1	RC	Quincy House, Room 108: Exit light inoperative	1	6-30-12	11/13/11	9
						10
					Pending	11
NFPA 1962, Ch. 4 & 5	ws	Gadsden Center General: Fire hose in cabinets to be inspected	2	6-30-12	Complete	12
NFPA 80, 15-2.3.3	RC	Gadsden Center, 1st Floor adjacent to elevator. Fire door propped open	1	6-30-12	Complete	13
FFPC 1, 13.3.3.2	RC	Gadsden Center, 1st Floor S. Stair: Pre-action system inspection overdue	1	6-30-12	Pending	14
69A-51.050(2)	RC	Gadsden Center, Boller Room: Boiler inspection certificate not located	1_	6-30-12		15
NFPA 25, 4.6	RC	Gadsden Center, Boiler Room: Drain from fire pump bearing drip stopped up	11	6-30-12	Complete	16
NFPA 25, 4.6	RC	Gadsden Center, Boiler Room: Red tag on sprinkler system	1	6-30-12	Complete	17
FFPC 1, 13.3.3.3		Gadsden Center, Ground Floor: 2 ceiling tiles missing in Server Room (sprinklered building)	0	6-30-12	Complete	18
FFPC 1, 13.3.3.3	RC	Gadsden Center, Ground Floor: Lobby & Room 100 have several missing ceiling tiles (sprinklered building)	0	6-30-12	Complete	19
FFPC 1, 10.19.5.1	RC	Gadsden Center, Room 108: Remove storage in mechanical room	0	6-30-12	Complete	20
FFPC 1, 13.3.3.3	RC	Gadsden Center, Room 112: Ceiling tile missing (sprinklered building)	1	6-30-12	Complete Complete	21
FPC 1, 13.3.3.3		Gadsden Center, Room 115: 3 missing ceiling tiles	0	6-30-12		22
FFPC 1, 13.3.3.3	RC	Gadsden Center, Room 206 & Communication Room: Several missing ceiling tiles (sprinklered building)	0	6-30-12	Complete	23
FPC 1, 11.1.5.2.2	RC	Gadsden Center, Room 303: Power strip plugged into extension cord	0	6-30-12	Complete	24
FPC 1, 4.5.8.1	RC	Gadsden Center, Rooms 101, 109, 208, 3rd Floor Hall South & EOC: Exit lights inoperable	0	6-30-12	Complete	25
FPC 1, 13.3.3.3	RC	Gadsden Center, Rooms 312, 313 & Men's and Women's Room: missing ceiling tiles (sprinklered building)	0	6-30-12	Complete	26
NFPA 2001, 6.1.1	RC	Gadsden Center, Server Room: FM 200 system inspection overdue		6-30-12	Complete	27
NFPA 80, 15-2.1.1	RC	Gadsden Center, South Stair: 3rd Floor door to stair has inoperable exit device - stuck open	0	6-30-12	Complete	28
NFPA 72, 4.4.3.5	ws	Gadsden Center: FACP in "trouble " condition	2	6-30-12	Complete	29
FPC 1, 4.5.8.1	ws	Gadsden Center: No break glass hammer for valve cabinet at First Floor Center Stair landing	2	6-30-12	Complete	30

CODE NUMBER SREF Ch. 5	Insp. Initials		Prior Times Cited	Deficiency Corrected By		Line Number
		Location, Deficiency Description		1	11/12/11	
5(16)(a)6a RC	RC	Wakulla Center SW: Remove storage from Mechanical Room	2	6-30-12	11/12/11	1
					Complete	2
5(17)(b)2c	RC	CCLA W-14: Main Electrical Room used for storage	2	6-30-12	Complete	3
5(8)(c)5 RC	RC	CCLA, Server Room: 1 1/4" high threshold creating trip hazard - add warning sign on door	1	6-30-12	Complete	4
						5
						6
					44115144	7
5(6)(c)	RC	Quincy House, Front Porch: Ballusters missing at handrail	1	6-30-12	11/15/11	8
						9
						10
						11
					0 11	12
(16)(b)6	RC	Gadsden Center, 1st Floor adjacent to elevator: Water cooler inoperative	1	6-30-12	Complete	13
i(1)(e)8i	RC	Gadsden Center, 1st Floor: Several stained ceiling tiles adjacent to elevator	0	6-30-12	Complete	14
(16)(b)6	RC	Gadsden Center, 2nd Floor adjacent to elevator. Water cooler inoperative	1	6-30-12	Complete	15
(1)(e)8g	RC -	Gadsden Center, Boiler Room: Almost ail lighting inoperable	0	6-30-12	Complete	16
(1)(e)8g	RC	Gadsden Center, Mezzanine Elevator Room: All lights inoperable	0	6-30-12	Complete	17
(1)(e)8i	RC	Gadsden Center, Room 301 Several broken & molding ceiling tiles	11	6-30-12	Complete	18
(1)(e)8g	RC	Gadsden Center, South Stair: Light fixture missing, several lights inoperable, and fluorescent light fixture hanging from one end	0	6-30-12	Complete	19
(8)(d)		Gadsden Center, South Stair: Window broken out between ground level and 1st Floor	0	6-30-12	Pending	20
						y-13
	\dashv					
		(4)				